

General Environmental Incident Summary

Incident: 3612 **Date/Time Notice:** 1/17/2015 1715 **DEM Incident No:**

Responsible Party: North Dakota Pipeline Company

Date Incident: 1/17/2015 **Time Incident:** 1715 **Duration:**

County: Nelson **Twp:** 152 **Rng:** 57 **Sec:** 6 **Qtr:** SW NW

Lat: 48.01496 **Long:** -98.01031 **Method:** Navigation quality GPS

Location Description: Approximately 1/8 mile west of Petersburg, ND.

Submitted By: Valerie Lavik

Affiliation: Employee

Address: 2505 16th St SW

City: Minot

State: ND

Zip: 58701

Received By:

Contact Person: Kevin Gault
2505 16th St SW
Minot, ND 58701-6947

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Pipeline Leak

Description of Released Contaminant: Crude Oil

Volume Spilled: 0.50 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

During an integrity dig, contaminated soil was discovered. Cause is to be determined.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Non

Action Taken or Planned:

Contaminated soil will be removed and hauled to an approved disposal facility.

Wastes Disposal Location: Clean Harbors

Agencies Involved: NDDDES, Local Law Enforcement

Updates

Date: 1/17/2015 **Status:** Reviewed - Assigned to NDDoH Division

Author: Washek, Sandi

Updated Volume:

Notes:

Integrity dig found contaminated soil, but amount is unknown. Sent to Division of Waste Management Underground Storage Tank Program

Date: 1/22/2015 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received phone call from company contact at 16:45. Contact provided information on spill incident and cleanup. Apparently, they were conducting integrity tools and runs testing on their 16-inch crude oil line and found some data areas that needed to be inspected. According to the company representative, the line was shut down for the inspections and when they dug to the line at the location specified in the report, they found a small area of impacted soils, which they reported to be approximately .5 gallon of crude oil-impacted soils. The impact was dug out, along with some deteriorated pipe coating, and placed within a berm on a liner and was going to be disposed of at a permitted facility. No further followup required at this time.